NTSB ID: SEA02LA048

Aircraft Registration Number: N24933

Occurrence Date: 03/04/2002

Most Critical Injury: None

Occurrence Type: Accident

Investigated By: NTSB

Location/Time

Nearest City/Place Longmont	State Zip Code CO 80503		Local Time 0945	Time Zone MST	
Airport Proximity: On Airport	Distance From Landing Facility:			Direction Fro	m Airport:

Aircraft Information Summary

- 1	· · · · · · · · · · · · · · · · · · ·										
ı	Aircraft Manufacturer	Model/Series	Type of Aircraft								
	Cessna	152	Airplane								

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 4, 2002, at 0945 mountain standard time, a Cessna 152, N24933, sustained substantial damage when it collided with a snow bank at Vance Brand Airport (2V2), in Longmont, Colorado. The student pilot, the sole occupant, was not injured. The aircraft is owned and operated by Air West Flight Center, Inc. of Longmont, Colorado, and was being operated as a visual flight rules (VFR) instructional flight under the provisions of Title 14 CFR Part 91. Visual meteorological conditions prevailed, and no flight plan was filed for the local flight.

The pilot reported that he was practicing touch-and-go landings on runway 29. He stated that the touch down and initial rollout were normal, but as the airplane decelerated it began to drift to the left of runway centerline. The pilot attempted to correct the situation with rudder inputs; however, the airplane continued to track to the left. The airplane departed the left side of the runway, collided with a three-foot snow bank, and nosed over. The airplane sustained substantial damage to the firewall and empennage.

At 0945 the Aviation Routine Weather Report (METAR) at Jeffco Airport (KBJC), located 16 nautical miles south of the accident site reported winds from 280 degrees at 10 knots, 80 statue miles visibility, scattered clouds at 20,000 feet, temperature 4 degrees Celsius, dew point minus 12 degrees Celsius, and an altimeter setting of 30.12 inches.

There was a Notice to Airmen (NOTAM-D) in effect for Vance Brand Airport between March 1, 2002 at 1147 and March 4, 2002 at 1223, for 1/2 inch of packed snow over ice and braking action poor.

The pilot reported on the NTSB Pilot/Operator Aircraft Accident Report Form no mechanical malfunctions or failures at the time of the accident.

NTSB ID: SEA02LA048

Occurrence Date: 03/04/2002

AVIATION Occurre				rence Type: Accident								
Landing Facility/Approach Information												
Airport Name			Airport ID:	Airport Eleva	tion	Run	way Used	Runwa	ay Lengt	:h	Runv	ay Width
Longmont, Vance Brand	2V2	5052 Ft	. MSL	. 29				75				
Runway Surface Type: Concrete												
Runway Surface Condition: Ice; Snowcompacted												
Type Instrument Approach: NONE	<u> </u>											
VFR Approach/Landing: Traffic Pa	attern											
Aircraft Information												
Aircraft Manufacturer				/Series						Numbe	r	
Cessna			152						1528	0457		
Airworthiness Certificate(s): Norm	al; Utility											
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No	Number of Seats:	2	Certifie	Certified Max Gross Wt.				1670 LBS Number			er of Engines: 1	
Engine Type: Reciprocating			Engine Manufacturer: Model/Series: Uycoming O-235-L2C							Rated Power: 110 HP		
- Aircraft Inspection Information							•					
Type of Last Inspection			Date of Last Inspection Time			Time Si	Since Last Inspection			Airfran	ne To	tal Time
100 Hour			Ho					ours Hours			Hours	
- Emergency Locator Transmitter (ELT) Information											
ELT Installed? Yes	ELT Operate	ed? Yes	5		ELT	Aided i	n Locating Ad	ccident S	ite? No)		
Owner/Operator Information												
Registered Aircraft Owner			Street A	Address 10383 N	85TI	1 ST						
AIR WEST FLIGHT CENTER	INC		City Stat								е	Zip Code
			LONGMONT									80503
Operator of Aircraft			Street A		: Rea	'd Aircr	aft Owner					
Same as Reg'd Aircraft Owner				Same as Reg'd Aircraft Owner City							е	Zip Code
Operator Does Business As:			0	perator Desig	nator Co	ode: W(JKV					
- Type of U.S. Certificate(s) Held: None												
Air Carrier Operating Certificate(s)	:											
Operating Certificate:	_			Operator (Certific	cate:						
Regulation Flight Conducted Under: Part 91: General Aviation												
Type of Flight Operation Conducted	d: Instructional											
]	FACTU	JAL REPO	RT - AVIAT	ION							Page 2

NTSB ID: SEA02LA048

Occurrence Date: 03/04/2002

AVIAT	Occurrence Type: Accident											
First Pilot Information												
Name					City			State	e Dat	e of Birth	Age	
On File					On File	le On File						31
Sex: M Seat Occupie	d: Left	Prir	ncipal Profes	own			Cert	ificate	Number:	On File		
Certificate(s): Student												
Airplane Rating(s): None												
Rotorcraft/Glider/LTA: Nor	Rotorcraft/Glider/LTA: None											
Instrument Rating(s): No	ne											
Instructor Rating(s): None												
Type Rating/Endorsement	for Accident/Ir	ncident Aircra	ft? Yes			Curre	ent Biennial	l Flight Re	eview'	?		
Medical Cert.: Class 3	Medica	al Cert. Statu	s: Valid Med	dicalw/ wa	aivers/lim		D	ate of Las	st Med	dical Exan	n: 07/2001	
							•					
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	A	Instrumen	Instrument Simulated		otorcraft	Glider	Lighter Than Air
Total Time	35	31	35									
Pilot In Command(PIC)	2	2	2						\bot			
Instructor	-				-				+			
Last 90 Days	15	15	15		1	_			+			
Last 30 Days Last 24 Hours	11 2	11 2	11			_			+			
Seatbelt Used? Yes	<u>' </u>	ılder Harness			To	xicology	y Performe	ed? No		Seco	nd Pilot? N o	
Coalbon Coca. 100	Onoc	ader Harriess	0300: 163			,,,,,,,,,,	,, 1 011011110	110		10000	101 1101. 140	
Flight Plan/Itinerary												
Type of Flight Plan Filed: N	lone											
Departure Point					s	tate	Airport Identifier Departure Time			e Time	Time Zone	
Same as Accident/Incid	ent Location					2V2			0915			MST
Destination					s	tate	Airport	irport Identifier				
Local Flight							, in port succession.					
Type of Clearance: None												
Type of Airspace: Class G												
Weather Information												
Source of Briefing: Commercial Weather Service; No record of briefing												
Method of Briefing: Telephone												
FACTUAL REPORT - AVIATION Page 3												

NTSB ID: SEA02LA048

Occurrence Date: 03/04/2002

Occurrence Type: Accident

	Occurrenc	Occurrence Type: Accident										
Weather Information												
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Di	istance Fro	m Accid	dent Site		Direction Fror	n Accident S	ite
KBJC	0945	MST	5670 Ft.	MSL				16 NM	170 Deg. Mag			g. <mark>Mag.</mark>
Sky/Lowes	st Cloud Condition: Scat	tered			20	0000 Ft. A	GL	Condition o	of Ligh	nt: Day		
Lowest Ce	Ft.	AGL	Visibi	ility:	80	SM	Altii	meter:	"Hg			
Temperatu	-12 °C	Wind	Direction:	280			Density Altitude: Ft.					
Wind Spee	ed: 10	Gusts:		Weath	ner Condti	ions at Acc	ident S	ite: Visual C	Cond	itions		
Visibility (F	RVR): Ft.	Visibility (RV	/V)	SM	Intensity	y of Precipit	tation:					
Restriction	s to Visibility: None											
Type of Pro	ecipitation: None											
Accident	Information											
Aircraft Dai	mage: Substantial		Aircraft Fire	e: None	ne Aircraft Explos					n None		
Classificati	on: U.S. Registered/U	J.S. Soil										
- Injury Su	mmary Matrix	Fatal Ser	ious Mino	or	None	TOTAL						
First Pi	lot				1	1						
Second	d Pilot						7					
Studen	it Pilot						7					
Flight I	nstructor						7					
Check	Pilot						7					
Flight E	Engineer											
Cabin A	Attendants											
Other C	Other Crew											
Passer	Passengers											
- TOTAL ABOARD -						1	ī					
Other 0	Ground					1						
- GRAND	O TOTAL -				1	1	ī					

TRANSPO

NTSB ID: SEA02LA048

National Transportation Safety Board	NIODID. GEAGZEAG40	1
FACTUAL REPORT	Occurrence Date: 03/04/2002	
AVIATION	Occurrence Type: Accident	
Administrative Information		
Investigator-In-Charge (IIC)		
Dennis J. Hogenson		
Additional Persons Participating in This Accident/Incident	dent Investigation:	